

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2005	DATE	Jan. 16. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Given certain unfavorable combinations of tolerances, the final drive can be subject to the occurrence of fretting corrosion between the inner bearing race of the needle roller bearing and the bearing seat of the input shaft. As the distance covered by the motorcycle increases, this can result in increased wear of the input shaft and, consequently, to excessive play at the rear wheel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F800S	BMW F800S	2006 - 2007	786
F800ST	BMW F800ST	2006 – 2009	801
		TOTAL	1,587