

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1999	DATE	January 16, 2014
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	For 7 speed S-tronic gearbox control unit, due to improper gear oil, electrical short circuit occurs on the power supply circuit and related fuses get cut. If the defect happens during drive, clutch will be disengaged, which leads loss of driving motive; consequently vehicle slowly loses momentum till completely stops and no further driving possible. Nevertheless, under this condition, brakes, steering, and all other related driving functions are still available to maneuver the vehicle toward safety stop. If the defect happens during stationary period, engine cannot be started or still no further driving possible even engine can be started.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8JCDA	TT Coupe 1.8	2013	335
DBA-8PCAX	A3 1.4TFSI	2013	1,930
DBA-8XCAX	A1 1.4/90kw	2013-2014	2,494
		Total	4,759