

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3287	DATE	Jan. 10 2014	
MANUFACTURER	MORITA-ECONOS CORPORATION			
DESCRIPTION OF DEFECT	<p>Since the process for drilling holes to attach jump seats on car floor panels was inadequate for home-visit bathing service cars, some pipes of the evaporative emission control through just below the mounting holes are damaged.</p> <p>In addition, the attaching bolts of the jump seats are interfered with the pipes among them.</p> <p>Therefore, there are risks of having holes and a leak of fuel evaporative emission into the air if you continue the use of them in such conditions.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
ABF-SKP2M	MAZDA BONGO	2012 , 2013	15	
ABF-SKP2V		2012 , 2013	67	
ABF-SKP2MN	NISSAN VANETTE	2013	1	
			TOTAL	83