

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|---|------|--------------------|
| CAMPAIGN No. | GAI-2012 | DATE | February. 27. 2014 |
| MANUFACTURER | Sundiro Honda Motorcycle Co., Ltd. | | |
| DESCRIPTION OF DEFECT | For front brake, the inner wire might have been cast into the cable end at an improper position. Through frequent repetition of the parking lever operation for the purpose of stopping or parking on a slope or the like, the cable end could be damaged, rendering the front brake ineffective. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|------------------|---------------------|-------------------|
| JBH-AA04 | SUPER CUB 50 MD | 2013 | 769 |
| EBJ-JA10 | SUPER CUB 110 MD | 2013 | 7,375 |
| | | TOTAL | 8,144 |