

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 3 2 1	DATE	Feb.25.2014
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to insufficient the retention force of the oil cooler hose for the automatic transmission of the ambulance, the hose comes off, and oil leak and the vehicles might not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-FPWGE50	「PARAMEDIC」	2013~2014	98
		TOTAL	98