## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3311	DATE	Feb.20.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	to the inadequate wiring of contact an EGR (Exhaust driving etc. Therefore, if	buses that equipped to color alternator harness, the Gas Recirculation) cooler the bus continues to be us cuit of the harness and, in the transfer of the harness and the harn	alternator harness may by the vibration of ed in this condition, it

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
SDG-RR7JJCA	[HINO Melpha]	2011~2012	28
SDG-RR7JJCAKAI			
		TOTAL	28