

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3308	DATE	February 19 2014
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	The position of the side reflectors on both sides for tractors (over 6m vehicle length) is not applied for the safety regulation for road vehicle article 35-2 (Side lamp and side reflector).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-GK6XAD-KAI QKG-GK6XAD-KAI	UD Trucks Quon	2011-2013	127
		Total	127