## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3309	DATE	Feb.18 2014		
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation				
DESCRIPTION OF DEFECT	On some heavy-duty hybrid regular-service buses, durability of the in hybrid system is insufficient. If the bus continues to be used condition, the inverter may break, and the powertrain drive motor for auxiliaries will become inoperative, causing illumination of the system warning lamp and lowering of powertrain output. In the we the power steering will become faulty or the bus itself will become drive.				

TYPE	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-MP37TK		2008~2010		3
BJG-MP37TM	「FUSO AERO STAR」	2008~2010		33
			TOTAL	36