

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3307	DATE	February 14 ,2014
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	Brake Plate, structure parts of braking device which avoid interference of brakeshoe and break plate, a designated groove in the brake plate was improperly set. When the stress of stretching and compression of braking are concentrated, crack will likely to appear in the groove, and then it will eventually have a possibility of brake malfunction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PLS341AH	—	2013	1
PLS752AA	—	2012	1
PMS232AA	—	2010	1
PMS232AB	—	2012	1
PMS241AE	—	2009	3
PMU241AA	—	2013	1
		TOTAL	8