

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|-------------|
| CAMPAIGN No. | 3 3 0 3 | DATE | Feb.13.2014 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | <p>Due to insufficient the retention force of the clamp for connecting the intercooler hose and the throttle chamber on the diesel turbo engine, if the vehicles continue to be driven in this condition, the vehicle may be poor acceleration due to the hose comes off by shake of the engine. In an extreme case, the engine may stall.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|-------------|------------------------------|---------------------|--------------------|
| LDF-VW2E26 | N I S S A N NV350 CARAVAN | 2012 ~ 2013 | 8,793 |
| LDF-VW6E26 | | | 6,442 |
| LDF-CW8E26 | | | 1,750 |
| LDF-CW4E26 | | | 917 |
| LDF-DW4E26 | | | 108 |
| LDF-JVW2E26 | I S U Z U COMO | | 219 |
| LDF-JVW6E26 | | | 184 |
| LDF-JCW8E26 | | | 13 |
| LDF-JCW4E26 | | | 23 |
| LDF-JDW4E26 | | | 1 |
| | | TOTAL | 18,450 |