

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3301	DATE	February 13, 2014
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	There is a possibility that the tractor will make an unintended quick turn if steering to the left shortly after steering to the right. This is because the travel control program is inappropriate in the transmission controller of the forward/reverse hydraulic clutch.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
T130F	「TPC153」	2003-2013	705
T147F	「TPC183」	2005-2013	678
		TOTAL	1383