

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3297	Date	13th Feb., 2014
Manufacture	Caterpillar Japan LTD		
Description of Deffect	A rear axle trunnion may be assembled without washers. The bolts may be loosened. Then the axle may come off from the frame.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-SAT	「910H」	2013	56
		TOTAL	56