

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3312	DATE	February.10. 2014
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>For hybrid-powered vehicles equipped with 7-speed dual-clutch automatic transmission (DCT), the transmission may have such a fault that the sleeve cannot move smoothly on the hub of the 1st gear. It can cause engagement failure of the 1st gear, which could cause the vehicle difficulty in starting off (i.e. the vehicle would take time to start off or would not start off) or cause the vehicle to roll down a slope or result in unusual acceleration (engine racing), or it can cause sudden engagement of the 1st gear, which could result in sudden start or other unintended movement of the vehicle. On such particular occasions, all the shift position lights on the meter display would come on, or the transmission warning light would blink and the meter display would indicate the need to have the transmission serviced.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-GP5	FIT	2013~2014	15,471
		2013~2014	52,550
		2013~2014	144
		2013	13
DAA-GP6		2014	2,732
		2014	19
DAA-RU3	VEZEL	2013~2014	7,050
DAA-RU4		2013~2014	3,374
		TOTAL	81,353