

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3334	DATE	March 28,2014
MANUFACTURER	HOWA MACHINERY,LTD.		
DESCRIPTION OF DEFECT	There is a possibility that the auxiliary dust sweeping side brushes on the underside of the road sweeper have not been attached properly. If the equipment continues to be used in this condition, there is a danger that the auxiliary side brushes may fall off the road sweeper.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90T2(KAI)	「FORWARD」	2013	9
TOTAL			9