

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~/~~ Import Vehicles

CAMPAIGN No.	Gai-2016	DATE	March 25, 2014
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	The affected motorcycles may have been built with an incorrectly programmed setting within the Body Control Module (BCM) that is set by Harley-Davidson. On these motorcycles, activating the brakes will illuminate both the amber rear turn signal lamps and red brake lamps. In this condition the rear lighting may not meet the regulation which requiring all brake lighting to be red.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FLHM	STREET GRIDE	2014 (MY)	13
		TOTAL	13