

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | Gai-2017 | DATE | Mar. 20, 2014 |
| MANUFACTURE | General Motors Company (Japanese Importer : General Motors Japan Ltd.) | | |
| DESCRIPTION OF DEFECT | General Motors has decided that a defect which relates to motor vehicle safety exists in 2006-2007 Chevrolet HHR. The ignition switch torque performance may not meet General Motors' specification. If the torque performance is not to specification, the ignition switch may unintentionally move from "run" position to the "accessory" or "off" position with a corresponding reduction or loss of power. This risk may be increased if the key ring is carrying added weight or the vehicle goes off road or experiences some other jarring event. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may result in the airbags not deploying, increasing the potential for occupant injury in certain kinds of crashes. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------|-----------------|---------------------|-------------------|
| --- | 「HHR」 | 2006-2007 | 173 |
| | | TOTAL | 173 |