

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3326	DATE	March.17.2014
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	In the worst case, there is the possibility DPF system will not function due to the generation of rust on the inside of the inlet manifold connected with the burner air pump of DPF system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS – NR6B	NR302	2013	36
UDS – NR6B	NRN302	2013	1
		TOTAL	37