

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3322	DATE	Mar. 11, 2014
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Water which infiltrates into the front left side door reaches to the door lock cable end, and it might freeze up in the cable.</p> <p>Therefore, with this condition, there is possibility that the door lock cable is stuck after opening the door and the door is not closed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA600S	TANTO	2013-2014	57,493
DBA-LA610S			11,420
		TOTAL	68,913