

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3316	DATE	Mar.11.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trucks equipped with a spring parking brake chamber on the front axle, due to the inadequate shape of the ABS control valve's bracket, the clearance between the spring parking brake chamber of the front axle's right wheel and the cover of the ABS control valve's bracket is narrow. Therefore, in case only the right wheel runs on a big bump under the laden condition, the parts above-mentioned may interfere and the spring parking brake chamber may be damaged. In the worst case, a wheel parking brake to be functioned by the leakage of the brake air resulting the vehicle unable to move.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FR1AKAA	[HINO Profia]	2010～2013	71
QKG-FR1AKAA			
LKG-FS1AKAA		2010～2013	1,273
QKG-FS1AKAA			
LDG-FS1APBA		2011～2013	61
LKG-FS1APBA			
QKG-FS1APBA			
LDG-FS1EKAA		2010～2013	1,901
LKG-FS1EKAA			
QKG-FS1EKAA			
LDG-FS1EPBA		2010～2013	437
LKG-FS1EPBA			
LKG-FS1EPBAKAI			
QKG-FS1EPBA			
QKG-FS1EPBAKAI			
		TOTAL	3,743