

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 3 2 5	DATE	M a r . 1 0 . 2 0 1 4
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the structure to raise and lower a parking stand (the stand to hold the body of the vehicle with the rear wheel keeping contact with the ground surface), due to an inadequate design, the parking stand cannot be lowered unless the brake lever for the rear wheel is grasped with a strong force at the maximum amount of pull or close to that. Therefore, each time the parking stand is used, the brake cable for the rear wheel is excessively pulled, and in the course of using the stand, the said cable may be cut and the rear brake may become ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B H - U A 0 6 J	GEAR BX50S	2 0 0 8 ~ 2 0 1 4	1 1 , 2 7 9
TOTAL			1 1 , 2 7 9