VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3323	DATE	Mar.6.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty sightseeing buses, in oil piping of the transmission, due to inadequate tightening of the connector attached to the oil filter, there are some from which oil leaks. If the vehicle is operated under the condition continuously, in the worst case, there is a possibility that the transmission is seizured and driving may become impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-RU8JHAA	[HINO SELEGA]	2010	33
LDG-RU8JHBA		2010~2014	163
SDG-RU8JHBA			
		TOTAL	196