

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3320	DATE	Mar 6, 2014
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	The seal rubber for shockabsorber was gradually deformed by its insufficient durability. It decreased sealing performance, resulting in oil leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-ER250C	「Z250」	2013	491
TOTAL			491