

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3315	DATE	Mar.6.2014
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain heavy duty sightseeing hybrid buses, due to inadequate program of vehicle control ECU, once ABS operates, even though it stops operating after that, the ECU could keep recognizing that the ABS is in operation rarely.</p> <p>Therefore, even if the engine retarder switch is operated in that condition, the engine retarder would be non-functional.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QQG-RU1ASBR	[HINO SELEGA]	2012~2013	15
		TOTAL	15