VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3351	DATE	April 22,2014		
MANUFACTURER	HOWA MACHINERY,LTD.				
DESCRIPTION OF DEFECT	Some of the vehicles do not meet safety standards when optional components(cabin) are attached to the motor sweeper. Some vehicles to which are attached optional accessories, do not meet: ①The safety regulation for road vehicle (article 5) because maximum stable inclination angle is less than 30 degrees. ②The safety regulation for road vehicle (article 45) because some vehicles do not equip automatic wipers for front window.				

TYPE	COMMERCIAL NAME	MOI YEA RECA	AR	NUMBER OF VEHICLE
HF66A		1988 ~	1995	17
HF66A2	$\lceil \mathrm{HF}66\mathrm{A} floor$	1995 ~ 1997		2
HF66A3		2005 ~ 2007		5
			TOTAL	24