

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic/Import Vehicles)

CAMPAIGN No.	3349	DATE	Apr 21,2014
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD.		
DESCRIPTION OF DEFECT	On some petroleum aluminum tank semi-trailers 20kL single axle, the bogie frame doesn't have enough durability. Therefore, crack damage may occur on such bogie frame due to the vibration during running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL20-17AS1	tank semi-trailer	2000	1
KL20-17AS2	tank semi-trailer	2000-2001	2
KL20-17AS3	tank semi-trailer	2000	2
KL20-17CS1	tank semi-trailer	2000-2001	4
KL20-47AS1	tank semi-trailer	2000-2004	5
KL20-47AS2	tank semi-trailer	2001-2005	12
KL20-17CS2	tank semi-trailer	2001-2002	2
KL20-17AS4	tank semi-trailer	2001-2006	14
KL20-17AS5	tank semi-trailer	2001	2
KL20-17AS6	tank semi-trailer	2003	1
KL20-17CS3	tank semi-trailer	2002-2007	8
KL20-17AS7	tank semi-trailer	2002	1
KL20-17AS9	tank semi-trailer	2004	1
KL20-17CS4	tank semi-trailer	2005	1
KL20-17AS91	tank semi-trailer	2005	1
KL20-17AA1	tank semi-trailer	2006	2
KL20-37AS1	tank semi-trailer	2006-2007	6
KL20-17AA2	tank semi-trailer	2006	3
KL20-37AS2	tank semi-trailer	2006	1
KL20-17AA3	tank semi-trailer	2007	1
KL20-17AA4	tank semi-trailer	2007	1
KL20-17AA5	tank semi-trailer	2007	2
KL20-47AS3	tank semi-trailer	2007	1
		TOTAL	74