

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2028	DATE	April 16 th 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>① Due to the inappropriate design of the coolant flow on the engine oil filter housing, coolant may enter in a space which is unexpected. In case of keep driving under such condition, the coolant in the unexpected space may expand by heat. This may damage the sealing and coolant will leak from that part. In worst case, overheat may occur.</p> <p>② Due to the assembling of the wrong parts on the grip plate, the illumination uniformity cannot be fulfilled, which does not meet the requirements defined in the Japanese safety regulation article 36.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XM15	「MINI Cooper」	2014	26
DBA-XM20	「MINI Cooper S」	2014	14
TOTAL			40