

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3350	DATE	Apr.15 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks, cracks may occur in the output shaft of the automated manual transmission due to insufficient strength of the shaft. If the truck continued to be used in this condition, the cracks will widen and, in the worst case, the output shaft will break. This will result in falling off of the propeller shaft, or letting the propeller shaft move roughly to damage the surrounding parts, causing secondary troubles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FU54JZ	「FUSO SUPER GREAT」	2007~2010	411
BKG-FU55JZ		2008~2010	69
LKG-FU54VZ		2010~2012	137
LKG-FU55VZ		2010~2012	28
QKG-FU54VZ		2012~2014	90
QKG-FU55VZ		2012~2014	42
		TOTAL	777