

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2019	DATE	Apr. 11, 2014
MANUFACTURE	General Motors Company (Dealer: YANASE GLOBAL MOTORS)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in 2013 and some 2014 model year Cadillac XTS vehicles. Pressure within the brake booster pump harness may cause a brake booster pump cavity plug to dislodge from the connector. This could allow contamination which may cause corrosion of the brake booster pump relay connector. If there is sufficient corrosion of the relay connector, it may cause a resistive short and melt the connector, which could cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	「XTS」	2013-2014	41
		TOTAL	41