## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2032	Date	May 14,2014		
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )				
Description of defect					
	3 A concern has been identified on certain Range Rover 2013 vehicles where the vehicle may not start due to an internal failure of the battery positive terminal. The vehicle battery located on the battery tray in the rear of the vehicle is not sufficiently isolated from the dynamic inputs experienced through 'normal' driving. These inputs result in an internal failure of the battery positive terminal and the vehicle will not start.				

Туре	Commercial name	Model year recalled		Number of vehicles
ABA-LG5NA	「Range Rover」	ge Rover」 2013		125
ABA-LG5SA	「Range Rover」	2013		64
			Total	189