

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2038	DATE	May 29th, 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The molding of the lever in the rear door lock mechanism, which deactivates the door latch from vehicle inside, is inappropriate. Thus, it may be the case that, when the activated child safety lock may be deactivated by operating the inner door handle. In worst case, the rear door can be opened.</p> <p>* Child safety lock: a mechanism which is to prevent downfall of the child, who is sitting on the rear seat, by operating the inner door handle.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KR30	BMW X5 xDrive 35i	2013 - 2014	62
LDA-KS30	BMW X5 xDrive 35d	2013 - 2014	137
LDA-KS30S		2013 - 2014	39
CBA-KR44	BMW X5 xDrive 50i	2014	5
TOTAL			243