

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3364	DATE	May 29 ,2014
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	It has been found that the heavy-duty trucks are provided with an inappropriate engine control program for DPD (Diesel Particulate Defuser) regeneration, which may increase piston temperature and cause an excessive thermal load on pistons. This may end up in the piston cracking and having a hole, which in turn may cause engine power loss and white smoke emission. In the worst case, the truck may become unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CXE77A OKG-CXE77A	[GIGA]	2010-2013	15
LKG-CXG77A OKG-CXG77A		2010-2013	53
LKG-CXM77A OKG-CXM77A		2010-2014	52
LKG-CXY77AJ OKG-CXY77AJ		2010-2014	63
LKG-CXZ77AT OKG-CXZ77AT		2010-2014	4,751
LKG-CYE77AZ OKG-CYE77AZ		2011-2013	24
LKG-CYG77AM		2010-2011	6
LKG-CYH77A OKG-CYH77A		2010-2014	266
LKG-CYJ77A LKG-CYJ77AA QKG-CYJ77A OKG-CYJ77AA		2010-2014	8,697
LKG-CYJ77AL OKG-CYJ77AL		2010-2013	30
LKG-CYJ77AZ OKG-CYJ77AZ		2010-2013	41
LKG-CYL77A LKG-CYL77AA QKG-CYL77A OKG-CYL77AA		2010-2014	4,795
LKG-CYL77AM OKG-CYL77AM		2010-2014	242
LKG-CYL77AZ OKG-CYL77AZ		2010-2014	77
LKG-CYM77A OKG-CYM77A		2010-2014	384
LKG-CYM77AM OKG-CYM77AM		2010-2014	312
LKG-CYM77AZ OKG-CYM77AZ		2010-2013	10
LKG-CYY77A OKG-CYY77A		2010-2014	356

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LKG-CYY77AJ OKG-CYY77AJ	[GIGA]	2010-2014	81	
LKG-CYY77AY OKG-CYY77AY		2010-2014	160	
LKG-CYY77AZ OKG-CYY77AZ		2010-2013	18	
LKG-CYZ77A OKG-CYZ77A		2010-2014	583	
LKG-CYZ77AJ OKG-CYZ77AJ		2010-2014	132	
LKG-CYZ77AM OKG-CYZ77AM		2010-2014	972	
LDG-CYZ77AMQ ODG-CYZ77AMO		2010-2014	52	
LDG-CYZ77AV ODG-CYZ77AV		2010-2014	44	
LKG-EXD77AD OKG-EXD77AD		2010-2014	256	
LKG-EXD77AG OKG-EXD77AG		2010-2014	187	
LKG-EXD77AL OKG-EXD77AL		2010-2014	18	
			TOTAL	22,677