

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3372	DATE	JUNE.19 2014
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>For selection of the Fixing pin attachment bolts of the suspension lock cylinder was inappropriate, there are cases where the bolt is loose, to fall off.</p> <p>If keep using with same condition, the Fixing pin attachment bolts of the suspension lock cylinder will fall off and it may damage hydraulic pressure hose which connecting with suspension lock cylinder.</p> <p>In the worst case, there is a possibility that oil will leak and the steering becomes impossible.</p> <p>Remedy</p> <p>The Fixing pin attachment bolts of the suspension lock cylinder replace bolt and washer assembly (with spring washer) for all vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-KRC011	KR-25H	2013~2014	423
TOTAL			423