VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2045	DATE	June 18, 2014
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper gearbox control unit program, shift position or clutch position may be interpreted wrongly during drive. As a result, gear holding symptom may occur; in the worst case, vehicle turns out as breakdown finally if clutch becomes open.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	「VW up! 1.0/55kW」	MY2013	5
DBA-AACHY	「VW up! 1.0/55kW」	MY2013-MY2014	18,271
		Total	18,276