

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3370	DATE	June 13.2014
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	In the rear tire portion of the tractor for agriculture, some axles have a shortage of strength that came from the inadequate hardness. It is because the heat treatment on the shaft was inappropriate. Therefore, if the unit is operated with the current parts, there is a possibility that the axle will break at the flange of the tire, which can cause the unit to become unable to travel in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
90A	AF890	2002~2004	214
MT90B	MT901	2002~2003	19
			TOTAL
			233