

VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2054	DATE	June 13.2014
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	The cooling water tube from the engine to the turbocharger damages by the strength lack and cooling water sometimes leaks out. Therefore, when continuing use in this condition, there is a fear that the engine becomes overheat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「JD-6140R」	2012~2013	8
-	「JD-6150R」	2013	86
-	「JD-6150M」	2012~2013	1
-	「JD-6170M」	2012~2013	2
TOTAL			97