

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3363	DATE	June 12,2014
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate structure of the base for the lighting switch platform, there may be the part where crack occurs in the soldering between the base and the platform caused by the repeated heating cycle of expansion and contraction. In the worst case scenario, the cracked portion could cause a temporal continuity failure resulting in the situation where the head lamps and/or turn signal lamps do not turn on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-H81W	「eK-SPORT」	2003~2004	12,838
UA-H81W	「eK-WAGON」 「eK-SPORT」 「eK-CLASSY」	2003~2004	75,703
CBA-H81W	「eK-WAGON」 「eK-SPORT」 「eK-CLASSY」 「eK-ACTIVE」	2004~2006	72,299
DBA-H81W	「eK-WAGON」 「eK-SPORT」 「eK-CLASSY」	2004~2006	90,979
CBA-H82W	「eK-SPORT」	2006~2008	7,071
DBA-H82W	「eK-WAGON」 「eK-SPORT」	2006~2008	91,848
TA-H53A	「PAJERO MINI」	2003~2005	4,275
ABA-H53A		2005~2008	1,766
TA-H58A		2003~2005	23,591
ABA-H58A		2005~2008	20,328
UA-Z25A	「COLT」	2003~2004	19,395
CBA-Z25A		2004	7,806
UA-Z26A		2003~2004	2,922
CBA-Z26A		2004	1,598
UA-Z27A		2003~2004	1,472
CBA-Z27A		2004~2006	2,463
CBA-Z27AG		2006~2008	1,423
CBA-Z27W		2004~2006	1,831
CBA-Z27WG		2006~2008	821
UA-Z28A		2003~2004	492
CBA-Z28A		2004	395
DBA-Z21A		2004~2008	38,517
CBA-Z22A		2004~2005	2,337
DBA-Z22A		2005~2008	3,758
DBA-Z23A		2004~2008	1,992
ABA-Z23A		2006~2008	348
DBA-Z23W		2004~2008	25,085

CBA-Z24A	「COLT」	2004～2005	232
DBA-Z24A		2005～2008	322
CBA-Z24W		2004～2005	2,853
DBA-Z24W		2005～2008	3,114
DBA-CS2A	「LANCER」	2005～2008	13,094
DBA-CS2W		2005～2007	2,045
DBE-CS2V		2005～2008	11,732
TA-CS5A		2005～2007	201
UA-CS5AR		2005	564
CBA-CS5AZ		2005～2008	1,831
LA-CS5W		2005～2007	3,298
TA-CS5W		2005～2007	244
CBA-CS6A		2005～2007	1,640
GH-CT9A		2005～2007	6,199
GH-CT9W		2005～2006	2,871
CBA-NA4W		「GRANDIS」	2004～2005
DBA-NA4W	2005～2008		6,461
LA-CU2W	「AIRTREK」	2004～2005	994
TA-CU2W		2004～2005	2,302
UA-CU5W		2004～2005	2,589
LA-V63W	「PAJERO」	2004～2006	509
LA-V73W		2004～2006	3,968
TA-V65W		2005	73
TA-V75W		2004～2005	194
ABA-V77W		2005～2006	174
TA-H76W	「PAJERO IO」	2005～2007	1,381
TA-H77W		2005～2007	3,144
CBA-H91W	「OTTI」	2005～2006	13,657
DBA-H91W		2005～2006	42,851
CBA-H92W		2006～2008	6,113
DBA-H92W		2006～2008	52,327
		TOTAL	704,449