

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2050	DATE	June 11, 2014
MANUFACTURER	KTM-Sportmotorcycle AG (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Because of improper tightening of the screw for securing the foot brake pedal on the footrest bracket, the screw will come loose rarely by continuous operation of rear brake and other reasons. As a result of this, the screw and the foot brake pedal fall off , then in worst case, the control of rear brake is lost.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
690ELET47	「690ENDURO R」	2014	21 UNITS
690SMCLST47	「690SMC R」	2014	34 UNITS
		TOTAL	55 UNITS