

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3366	DATE	Jun. 4, 2014
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	<p>In the diesel engine of the crop-dusting vehicle, if the wrong part (obsolete part) of the radiator-lower-hose, which has a different shape in comparison with the normal part, was attached, the hose might touch with the driving belt of the operating pump. And if the wrong radiator-lower-hose was used continuously, the hose might be damaged and coolant water might leak out, and finally the diesel engine might be overheated in a worst-case situation.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-H0	「3S-FSC641」	2013-2013	3
	「3S-FSC1041」	2012-2014	15
TOTAL			18