

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 0 8	DATE	Jul 31,2014
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Due to unsuitable routing of the travel brake hose on the braking device of wheel cranes, there are cases where, when the steering wheel is turned, the handle link mechanism may come in contact with the brake hose.</p> <p>Therefore, with continued use in this condition, there is a risk that the brake hose may be damaged and leak brake fluid leading to a reduction in braking force.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T008	TADANO 「GR-700N-1」	2013-2014	205
JDS-T004	TADANO 「GR-600N-2」	2008-2013	452
		TOTAL	657