

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 0 7	DATE	Jul 31,2014
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Due to a lack of durability of the wheel installation hub bolts on wheel crane's travel devices, there are cases where the bolt extends when the wheel nut is tightened.</p> <p>Therefore, there is the risk that the wheel nut cannot be tightened to the standard torque.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T009	TADANO 「GR-160N-3」	2013-2014	89
UDS-EW07	KOBELCO 「RK160-7」	2014	18
		TOTAL	107