

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3402	DATE	July 29 2014
MANUFACTURER	UD TRUCKS CO.,LTD.		
DESCRIPTION OF DEFECT	On certain medium duty trucks, heavy and medium duty buses, the pistons of engines could be machined inappropriately, and the form of the parts for piston-cooling (wear resistant ring) casting at the time of manufacturing is inadequate, causing internal separations of the piston walls and cracks on certain occasions. In extreme circumstances, there is a possibility for an engine failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-LK36A	Nissan Diesel Condor	2004-2006	78
BDG-LK36C	Nissan Diesel Condor	2006-2007	139
PB-LK37A	Nissan Diesel Condor	2006-2006	6
BDG-LK37C	Nissan Diesel Condor	2006-2007	9
PB-MK35A	Nissan Diesel Condor	2004-2006	1,176
BDG-MK35C	Nissan Diesel Condor	2006-2007	161
PB-MK36A	Nissan Diesel Condor	2004-2006	1,566
PB-MK36B	Nissan Diesel Condor	2005-2005	2
BDG-MK36C	Nissan Diesel Condor	2006-2007	1,275
BDG-MK36D	Nissan Diesel Condor	2006-2007	141
PB-MK37B	Nissan Diesel Condor	2004	1
BDG-MK37C	Nissan Diesel Condor	2006-2007	283
BDG-MK37D	Nissan Diesel Condor	2006-2007	152
PK-PK36A	Nissan Diesel Condor	2005-2006	68
BDG-PK36C	Nissan Diesel Condor	2006-2007	82
PK-PK37A	Nissan Diesel Condor	2004-2006	8
BDG-PK37C	Nissan Diesel Condor	2006-2007	263

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-PK37D	Nissan Diesel Condor	2006-2007	72
PK-PW37A	Nissan Diesel Condor	2006	1
BDG-PW37C	Nissan Diesel Condor	2006-2008	184
PK-JP360NAN PK-JP360NAN KAI	Nissan Diesel Space Runner	2004-2007	88
PB-RM360GAN PB-RM360GAN KAI	Nissan Diesel Space Runner	2004-2007	202
PB-RM360HAN PB-RM360HAN KAI	Nissan Diesel Space Runner	2004-2007	109
PK-RP360GAN	Nissan Diesel Space Runner	2006-2007	25
		TOTAL	6,091