

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3401	DATE	July 29 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy and medium duty buses, the pistons of engines could be machined inappropriately, and the form of the parts for piston-cooling (wear resistant ring) casting at the time of manufacturing is inadequate, causing internal separations of the piston walls and cracks on certain occasions. In extreme circumstances, there is a possibility for an engine failure.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU8JHAJ BDG-RU8JHAJ	[ISUZU GALA]	2006-2007	66
PB-RR7JJAJ	[ISUZU GALA MIO]	2004-2007	319
		TOTAL	385