

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2071	DATE	Jul. 29, 2014
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	2014 MY Fiesta / Fuel Delivery Module Inspection / Replacement  Certain 2014 Model Year Fiesta 1.0L vehicles built in Cologne between 6th January, 2014 through 07th May, 2014. A number of Fiesta 1.0L vehicles may have been fitted with a fuel pump that does not meet material specification. An affected pump will fail causing engine stall or non-start due to fuel starvation. Dealers are required to complete the following. - Inspect Fuel Pump / Sender unit assembly label date - If required Inspect the Fuel Pump batch date on the Pump - If required replace the Fuel Pump / Sender unit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-WFOSFJ	Ford Fiesta, 1.0L	2014	43 units
TOTAL			43 units