

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3392	DATE	July, 24, 2014
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The adopter of HST transmission oil filter is not durable enough, so that may lead to loose the oil filter and oil leak. Then it makes the driving problem.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-KL3N	「KL31Z」	2012～2013	459
	「KL34Z」	2012～2013	649
EDM-KL3K	「KL37Z」	2013	344
	「KL40Z」	2011～2013	1,028
	「KL44Z」	2011～2013	1,416
	「T2200KLZ」	2011～2013	124
EDM-KL3L	「KL48Z」	2011～2013	678
KDN-KL3M	「KL53Z」	2011～2013	1,794
	「KL58Z」	2011～2013	955
		TOTAL	7,447

