VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3393	DATE	Jul 17, 2014	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Piston in a wheel cylinder of the main brake system for rear wheels, can get some rust that invading water into the cylinder from the environmental air makes while using the car, because of insufficient rust-prevention ability of the piston. Therefore the seal of the cylinder can be scratched with the piston motion becoming unsmooth, the brake fluid can leak and the brake warning light comes on. In the worst case, the brake force might decrease.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-XB32S	SPLASH	From 2008 to 2014	17,004
		TOTAL	17,004