

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2051	DATE	July. 15. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Fuel-pump units and additional pump units (only R 1200 GS and R 1200 GS-A) might suffer from cracking at the mounting dome for the quick-action coupling. In very rare cases leaks can occur with a perceptible odor of fuel or the escape of fuel in small quantities.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HP2	BMW HP2 Enduro	2006	176
HP2-MM	BMW HP2 Megamoto	2008	119
HP2 SP	BMW HP2 Sport	2008-2010	149
R1200S	BMW R1200S	2006-2007	302
R1200ST	BMW R1200ST	2005-2007	901
R1200RT	BMW R1200RT	2005-2010	2088
EBL-R12JA	BMW R1200RT	2011	212
R1200GS	BMW R1200GS	2005-2010	2585
EBL-R12JA	BMW R1200GS	2011	177
R1200GS-A	BMW R1200GS-A	2006-2010	1074
EBL-R12JA	BMW R1200GS-A	2011	87
R1200R	BMW R1200R	2006-2010	979
EBL-R12JA	BMW R1200R	2011	188
K1200R-S	BMW K1200R-S	2006-2007	211
K1200S	BMW K1200S	2004-2008	1216
K1200R	BMW K1200R	2006-2008	614
K1200GT	BMW K1200GT	2006-2008	481
K1300S	BMW K1300S	2008-2010	419
EBL-K13AA	BMW K1300S	2011	92
K1300R	BMW K1300R	2008-2010	297
EBL-K13AA	BMW K1300R	2011	76
K1300GT	BMW K1300GT	2008-2010	234
S1000RR	BMW S1000RR	2009-2011	801
EBL-K16AA	BMW K1600GTL	2011	145
		TOTAL	13,623