

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3389	DATE	July 10. 2014
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For the swing lock mechanism which keeps the vehicle body upright while the parking brake is applied, its support bracket may have been machined inadequately and the swing lock pawl may be thereby not completely engaged with the locking pawl of the swing lock plate. If the parking brake is released or otherwise operated repeatedly with the locking pawl of the swing lock plate highly loaded due to such incomplete engagement, the locking pawl of the swing lock plate can suffer premature wear. Continued use in such a condition could, if the worse came to the worst, result in inclination of the vehicle body in spite of the parking brake application.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-TA03	GYRO CANOPY	2011～2013	5,411
JBH-TD02	GYRO X	2011～2013	3,516
		2012～2013	182
		TOTAL	9,109