

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3379	DATE	2014.7.2
MANUFACTURER	ASAMA AUTOMOTIVE PARTS CO., LTD.		
DESCRIPTION OF DEFECT	On the brake device in the passenger seat of an driving instruction car, since the snap pin which prevents the penetration rod pin of a brake pedal device from coming off was unsuitable, The snap pin extremely rarely came off from the penetration rod pin. Under these circumstances, the penetration rod pin may come off and instruction break system may not operate properly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE141	「COROLLA Axio」	2009 ~ 2012	114
DAA-NHW20	「PRIUS」	2009 ~ 2012	4
DAA-ZVW30	「PRIUS」	2009 ~ 2014	160
UA-NZT240	「ALLION」	2012	2
DBA-NZE161	「COROLLA Axio」	2012 ~ 2014	75
DBA-NRE160	「COROLLA Axio」	2013	8
DAA-NKE165	「COROLLA Axio」	2013	4
DBA-KEEFW	「CX-5」	2014	1
DAA-BYFP	「AXELA」	2014	1
DBA-SC11	「TIDA LATIO」	2011 ~ 2012	2
ZAA-ZE0	「LEAF」	2011	17
DBA-N17	「LATIO」	2013	8
DAA-FD3	「CIVIC HYBRID」	2009	10
DAA-ZE2	「INSIGHT」	2010 ~ 2011	11
DAA-GP2	「FIT SHUTTLE」	2012 ~ 2013	44
DBA-YC11S	「SX4」	2013	5
		TOTAL	466