

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN NO.	3409	DATE	Aug 1st 2014
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>On the steering system of the combine harvester, the adjustment of the micro-switches which detect the steering lever position may be improper. Due to above mentioned cause, the steering system may not work properly during the operation of the steering lever.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VC14D	「 V211 」	2013 - 2014	36
	「 V214 」		32
VC19A	「 V217 」		85
	「 V319 」		40
		TOTAL	193