

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2077	DATE	August 7, 2014
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Atlantic Cars Limited, Shintoyo Enterprises Ltd, Hakko LR Co., Ltd.)		
DESCRIPTION OF DEFECT	On the transmission, the transmission control switches could be electrically shorted through vehicle vibration etc due to design issue with the printed circuit board. If electrically shorted, the transmission will automatically engage Neutral and the drive operation cannot be maintained. Even if this is happened, the braking and steering control will be maintained to be safety stopped.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	DB9 Coupe, DB9 Volante	2013-2014	26
	Rapide S	2013-2014	32
		TOTAL	58